



Township N° X North, Range N° IV West of 2nd Meridian. Surveyed by James Holmes 1814

Description of the Soil on the interior Sectional lines.

Total 22,797.86

Between Sections	Quality &c.	Between Sections	Quality &c.	Between Sections	Quality &c.
35.36	Middling land - Timber Beech, Sugar, Ash	27.3	Wet land - Timber Beech, Poplar Sugar	17.19	Broken land - Timber Beech, Sugar, Poplar &c.
25.36	Same	33.34	Same	21.3	Broken land - Timber Beech, Sugar
25.26	Poorilly Honey land	27.34	Wet land - Timber Beech, Sugar	21.32	Same
25.24	Wetilly Honey land - Timber Oak, Sugar	27.15	Wetilly Honey land - Timber Same	29.32	Same
24.25	Wetilly land - Timber Oak, Beech	27.27	Same	31.32	Wetilly land - Timber Oak, Beech, Sugar &c.
13.24	Wetilly land - Timber Oak & Hickory	21.27	Wetilly rich land - Timber Sugar, Oak, Beech, Poplar	26.30	Same
13.24	Poorilly land - Timber Oak, Beech &c.	15.22	Poorilly strong land - Timber W. Oak, Hickory	20.29	Wetilly land - Timber Beech, Oak & Hickory
13.13	Same	15.16	Poor broken land - Timber, Beech, W. Oak, Hickory	19.36	Same
11.13	Wetilly land - Sugar Oak, Beech, Hickory	10.13	Same	19.10	Land of middling Quality - Timber Beech, Sugar &c.
1.13	Wetilly land - Timber Oak, Beech, Sugar	9.10	Wetilly land - Timber Oak & Beech	17.20	Same
1.2	Same	5.10	Same	15.19	Middling land - Timber Same
34.35	Same	5.11	Wetilly land - Timber Oak, Beech, Sugar &c.	17.15	Rich Wetilly land - Timber Sugar
26.35	Middling good land - Timber Oak & Sugar	32.32	Wetilly rich land - Timber Sugar, Beech	8.17	Same
26.27	Same	25.32	Rich Wetilly land	7.13	Middling good land - Beech, Sugar, Oak
25.26	Wetilly land - Timber Beech, Oak, Sugar &c.	25.20	Wetilly rich land - Timber Beech, Sugar &c.	7.3	Second rate land - Timber Same
22.25	Poorilly land - Timber Oak, Beech &c.	21.28	Wetilly rich land - Timber Beech, Sugar &c.	5.8	Same
14.13	Same	20.25	Wetilly land - Timber Beech, Oak	6.7	Second rate land - Timber Beech, Sugar, Poplar
14.13	Same	16.25	Same	5.6	Middling land - Timber of 11. above
11.14	Poor broken land - Timber Beech, W. Oak	16.17	Same		
10.11	Wetilly land - Timber Beech, Sugar	9.16	Broken land - Timber Beech, Sugar, Poplar		
2.11	Same	5.9	Same		

Township 18.00 North, Range 18.00 West of 1st Meridian Interior Section Corners described Interior Quarter Section Corners described

Section	Tree	Feet	Course	Feet	Quality of the Soil	Section	Tree	Feet	Course	Feet	Quality of the Soil	Section	Tree	Feet	Course	Feet	Quality of the Soil
A	Sugar	18	S 12 E	21		25	26	35	36	N. Oak	24	North	12	1	1	1	
a	do	18	S 12 E	21		25	26	35	36	Sugar	24	S 12 E	21	2	2	2	
B	Beech	8	S 33 E	27		25	26	35	36	do	24	S 33 E	27	3	3	3	
b	do	8	S 33 E	27		25	26	35	36	do	24	S 33 E	27	4	4	4	
C	Beech	9	S 38 E	23		25	26	35	36	do	24	S 38 E	23	5	5	5	
c	do	9	S 38 E	23		25	26	35	36	do	24	S 38 E	23	6	6	6	
D	Beech	24	S 23 E	30		25	26	35	36	do	24	S 23 E	30	7	7	7	
d	do	24	S 23 E	30		25	26	35	36	do	24	S 23 E	30	8	8	8	
E	Sugar	12	S 34 E	20		25	26	35	36	do	24	S 34 E	20	9	9	9	
e	do	12	S 34 E	20		25	26	35	36	do	24	S 34 E	20	10	10	10	
F	Beech	16	S 31 E	24		25	26	35	36	do	24	S 31 E	24	11	11	11	
f	do	16	S 31 E	24		25	26	35	36	do	24	S 31 E	24	12	12	12	
G	do	16	S 31 E	24		25	26	35	36	do	24	S 31 E	24	13	13	13	
g	do	16	S 31 E	24		25	26	35	36	do	24	S 31 E	24	14	14	14	
H	do	16	S 31 E	24		25	26	35	36	do	24	S 31 E	24	15	15	15	
h	do	16	S 31 E	24		25	26	35	36	do	24	S 31 E	24	16	16	16	
I	do	16	S 31 E	24		25	26	35	36	do	24	S 31 E	24	17	17	17	
i	do	16	S 31 E	24		25	26	35	36	do	24	S 31 E	24	18	18	18	
J	do	16	S 31 E	24		25	26	35	36	do	24	S 31 E	24	19	19	19	
k	do	16	S 31 E	24		25	26	35	36	do	24	S 31 E	24	20	20	20	
L	do	16	S 31 E	24		25	26	35	36	do	24	S 31 E	24	21	21	21	
M	do	16	S 31 E	24		25	26	35	36	do	24	S 31 E	24	22	22	22	
N	do	16	S 31 E	24		25	26	35	36	do	24	S 31 E	24	23	23	23	
O	do	16	S 31 E	24		25	26	35	36	do	24	S 31 E	24	24	24	24	
P	do	16	S 31 E	24		25	26	35	36	do	24	S 31 E	24	25	25	25	
Q	do	16	S 31 E	24		25	26	35	36	do	24	S 31 E	24	26	26	26	
R	do	16	S 31 E	24		25	26	35	36	do	24	S 31 E	24	27	27	27	
S	do	16	S 31 E	24		25	26	35	36	do	24	S 31 E	24	28	28	28	
T	do	16	S 31 E	24		25	26	35	36	do	24	S 31 E	24	29	29	29	
U	do	16	S 31 E	24		25	26	35	36	do	24	S 31 E	24	30	30	30	
V	do	16	S 31 E	24		25	26	35	36	do	24	S 31 E	24	31	31	31	
W	do	16	S 31 E	24		25	26	35	36	do	24	S 31 E	24	32	32	32	
X	do	16	S 31 E	24		25	26	35	36	do	24	S 31 E	24	33	33	33	
Y	do	16	S 31 E	24		25	26	35	36	do	24	S 31 E	24	34	34	34	
Z	do	16	S 31 E	24		25	26	35	36	do	24	S 31 E	24	35	35	35	

Corners on White River

Path	Tree	Feet	Course	Feet	Quality of the Soil
1	Buckeye	8	Corner		
2	do	36	S 19 W	25	
3	do	12	S 19 E	24	
4	do	14	S 56 W	13	
5	do	4	S 52 E	32	
6	do	11	S 11 W	11	
7	do	4	East	14	
8	do	12	S 52 W	17	
9	do	48	S 22 E	28	
10	do	16	East	15	
11	do	6	S 49 W	14	
12	do	18	S 2 E	12	
13	do	6	S 14 E	29	
14	do	35	S 64 W	10	
15	do	10	S 41 E	34	
16	do	2	S 56 E	25	
17	do	4	S 56 E	23	
18	do	8	S 57 E	19	
19	do	10	S 51 W	21	
20	do	4	S 55 E	15	
21	do	12	S 64 E	25	
22	do	8	East	3	
23	do	10	S 65 E	37	
24	do	7	S 22 E	15	
25	do	12	S 51 W	5	
26	do	8	East	9	
27	do	14	S 30 E	22	
28	do	10	S 13 W	10	
29	do	4	S 9 E	5	
30	do	15	S 72 E	5	
31	do	15	S 72 E	5	
32	do	15	S 72 E	5	
33	do	15	S 72 E	5	
34	do	15	S 72 E	5	
35	do	15	S 72 E	5	
36	do	15	S 72 E	5	
37	do	15	S 72 E	5	
38	do	15	S 72 E	5	
39	do	15	S 72 E	5	
40	do	15	S 72 E	5	

Interior Quarter Section Corners described

Section	Tree	Feet	Course	Feet	Quality of the Soil
1	Beech	20	S 18 W	25	
2	do	18	S 20 W	22	
3	do	12	S 38 W	19	
4	do	8	S 26 E	18	
5	do	10	S 30 W	21	
6	do	12	S 40 E	12	
7	do	15	S 12 E	28	
8	do	20	S 21 E	7	
9	do	12	S 13 W	30	
10	do	12	S 3 E	9	
11	do	18	S 10 W	5	
12	do	30	S 47 W	30	
13	do	9	S 50 E	31	
14	do	10	S 10 E	10	
15	do	4	S 38 E	18	
16	do	20	South	20	
17	do	4	S 36 E	19	
18	do	15	South	3	
19	do	24	North	20	
20	do	24	S 45 W	35	
21	do	5	S 3 E	5	
22	do	12	S 4 W	15	
23	do	12	S 4 W	15	
24	do	12	S 4 W	15	
25	do	12	S 4 W	15	
26	do	12	S 4 W	15	
27	do	12	S 4 W	15	
28	do	12	S 4 W	15	
29	do	12	S 4 W	15	
30	do	12	S 4 W	15	

Interior Quarter Section Corners described


Section	Tree	Feet	Course	Feet	Quality of the Soil
1	Sugar	8	S 20 W	27	
2	do	3	S 45 W	4	
3	do	4	S 27 E	5	
4	do	5	S 15 W	16	
5	do	8	S 5 E	12	
6	do	24	S 10 E	29	
7	do	8	S 80 W	5	
8	do	12	S 10 W	12	
9	do	15	S 75 W	13	
10	do	15	S 20 E	31	
11	do	32	S 30 W	34	
12	do	15	S 35 W	14	
13	do	9	East	21	
14	do	32	S 35 E	28	
15	do	12	S 35 W	26	
16	do	15	S 47 W	7	
17	do	12	S 19 E	32	
18	do	20	S 78 E	38	
19	do	4	S 10 W	5	
20	do	20	S 30 W	12	
21	do	20	S 15 E	20	
22	do	24	S 10 E	5	
23	do	5	North	32	
24	do	20	S 10 W	22	
25	do	24	S 30 E	20	

Corners on White River

Section	Tree	Feet	Course	Feet	Quality of the Soil
1	Cottonwood	12	S 5 E	9	
2	do	12	S 64 W	18	
3	do	5	S 33 E	16	
4	do	8	S 25 E	17	
5	do	14	S 56 W	13	
6	do	7	S 82 E	24	
7	do	8	Corner		
8	do	36	S 19 W	25	
9	do	12	S 19 E	64	

HQ

Township N.º 10 North, Range N.º 4 West, 2nd. Mer.




Surveyed in 1814 by James Holmes Deputy Surveyor.


I certify that the above is a true copy of the
recorded plat, in this Office.

Surveyor General's Office,
Cincinnati, Sept. 2, 1837.

Robert Lyth
Sur. Genl

Township No. 10 N. Range No. 4 W. 9th Mer.






TOWNSHIP, N^o X, RANGE, N^o W, 2nd PM Scale of Forty Chains to an inch


Certified the 17th day of June 1814 by

Surveyor General's Office
June 20th A.D. 1815

Samy Holmes D^y
Law and Officer Surveyor Gen^l



Township No. 10 N. Range No. 4 W. 2nd Mer.



TOWNSHIP, No. 10 N., RANGE, No. 4 W., 2nd Mer.

Certified the 17th day of June 1814 by

Surveyor General's Office
June 20th A.D. 1815

James Holmes D.S.
Surveyor General

Scale of Fifty Chains to an inch